

# Mishaps for FY-2003

Total	Mishap Type	Mishap Cause
191	DETONATION	DESIGN DEFICIENCY
		ENVIRONMENT
		MATERIAL FAILURE
		OTHER
		PERSONNEL ERROR
319	INDUCED DEFECT	DESIGN DEFICIENCY
		ENVIRONMENT
		MATERIAL FAILURE
		PERSONNEL ERROR
949	MALFUNCTION	DESIGN DEFICIENCY
		ENVIRONMENT
		MATERIAL FAILURE
		OTHER
		PERSONNEL ERROR
585	OBSERVED DEFECT	DESIGN DEFICIENCY
		ENVIRONMENT
		MATERIAL FAILURE
		PERSONNEL ERROR

2044

## Mishap Type

